

## MARYLAND DEPARTMENT OF THE ENVIRONMENT

1800 Washington Boulevard • Baltimore MD 21230 410-537-3000 • 1-800-633-6101 • www.mde.state.md.us

Martin O'Malley Governor Robert M. Summers, Ph.D. Secretary

Anthony G. Brown Lieutenant Governor

September 11, 2012

Lorie Baker Site Assessment and Non-NPL Federal Facilities Branch (3HS12) US EPA Region III 1650 Arch Street Philadelphia, PA 19103-2029

RE: Pre-CERCLIS Screening Report for Anderson Co., Hagerstown, Washington County, MD

Dear Ms. Baker:

Enclosed are the Pre-CERCLIS screening report and Site Discovery forms for the Anderson Co. by the Maryland Department of the Environment, Federal Assessment and Remediation Division (MDE). The report addresses a site identified in the *Maryland Dry Cleaner Initiative* report.

The objectives of the Pre-CERCLIS screenings are to categorize those sites identified in recent site initiatives which, (1) may need further investigation, and (2) need no further investigation. MDE performed screenings for the site and determined that there is sufficient cause to proceed with further investigation.

The enclosed Pre-CERCLIS Screening Report is submitted in accordance with the current cooperative agreement. If you have additional questions concerning this matter, please contact me at (410) 537-3399.

Sincerely,

Dixon Wood, CPG

Project Manager

Federal Assessment and Remediation Division

Enclosure

cc: Mr. Horacio Tablada

Mr. James Carroll Ms. Peggy Williams

rī.					
ě					
a a					
.24					
				1.60	
					9
					.80
	x				
	*				
	x				
	x				
	x				
	x				
	x				

United States Environmental Protection Agency

## POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION						
01 ST	02 SITE NUMBER					
MD						

Protection Agency SITE IDENTIFICATION ("DISCOVERY")					MD			
II. SITE NAME A	ND LOCATION			8				
01 SITE NAME (Legal, common, or descriptive name of site)				EET, ROUTE NU	MBER, OR	SPECIFIC LOCATION IDEN	TIFIER	
Anderson Co.			104-	110 East W	Vashin	gton Street		
03 CITY			04 ST	05 ZIP CODE			07 CO CODE	08 CONG DIST
Hagerstown			MD	21740	Wasi	hington		
	arting from nearest public road; enter up	to 4 lines of text)	1.12	217.10	1,, 4,52	8		
Potomac Street sou	ke exit 32, 40 N north (Buth to a left on East Wast on the left (north) side (	shington Street.						
III. RESPONSIBL	E PARTIES							
01 OWNER (If known)			02 STRE	EET (Business, re	esidential, ı	mailing)		
03 CITY			04 ST	05 ZIP CODE	06 TELE	EPHONE NUMBER		
			1		-			
			-	l .				
07 OPERATOR (If known and	different from owner)		08 STRE	EET (Business, re	esidential, r	mailing)		
).								
09 CITY		- T	10 ST	11 ZIP CODE	12 TELE	EPHONE NUMBER		
13 TYPE OF OWNERSHIP (Ma	ark one; use "insert" mode)							
A. PRIVATE E. MUNICIPAL	_ B. FEDERAL (Agency _ F. OTHER (Specify): _	rname):			_ C. ST. ☑ G. UN	ATE IKNOWN	_ D. COUNT	Υ
IV. HOW IDENTIFI	IED		740			Y		
01 DATE IDENTIFIED	02 IDENTIFIED BY (Mark all that appl	ly; use "insert" mode)						
June 2008	_ A. CITIZEN COMPLAINT		INDUST			C. STATE/LOCAL GOV		
(Month/Day/Year)	_ D. AERIAL RECONNAISS _ G. OTHER EPA IDENTIFI		RCRA II OTHER	NSPECTION (Specify): <u>D1</u>		F. SURFACE IMPOUN ner Initiative	DMENT ASS	ESSMENT
V. SITE CHARACT	<b>TERIZATION</b>	y y			'			
01 TYPE OF SITE (Mark all tha	at apply; use "insert" mode)							
A. STORAGE	B. TREATMENT	OSALD.U	NAUTH	ORIZED DU	MPING	E. OTHER (Specify,	:	
02 SUMMARY OF KNOWN PR	ROBLEMS (Provide narrative description	; enter up to 6 lines of te	ext)					
2 12	N							
03 SUMMARY OF ALLEGED	OR POTENTIAL PROBLEMS (Provid	le narrative description:	enter up to	5 lines of text)				
	ed for over 50 years as a				otentia	l exists for vapor	intrusion in	nto adjacent
VI INFORMATIC	ON AVAILABLE FROM							
01 CONTACT	ATTITUDE TROP	02 OF (Agency/Organiz	ivertical 02			03 TELEPHON	E NUMBER	
Dixon Wood MDE - LRP							410-537-3	
04 PREPARED BY		05 AGENCY	OS OPG	ANIZATION		07 TELEPHONE NUMBR	08 DATE (Mont	
Dixon Wood		MDF.	I.RP			410-537-3399	9/6/2012	

Location	onal Data (please enter either	format and WasteL	AN will cor	vert what is	entered into the seco	and format	:)	
Latitue	le: 39.640699	Longitude -7'	7.717828		Format	□ Degre	es Minutes S	Seconds
					☐ Decimal			
Acura	y Meters+/-:3	Collection Date	e: <u>9</u> / <u>6</u>	/ 2012	Reference Datum:	NAD27	NAD 83	OTHER
					UNKNOWN WO	GS84		·
Collect	ion Method (Select one from	below)						*
	Address Matching – House No	,			☐ Interpolation –	Digital M	ap Source (T	IGER)
	Address Matching – Block Fa	ce			☐ Interpolation –	Мар	•	,
	Address Matching - Street Ce	nterline		4	☐ Interpolation –	Photo		
	Address Matching – Nearest I	ntersection			☑ Interpolation –	Satellite		
	Address Matching – Primary 1				☐ Interpolation –	Other		
	Address Matching – Digitized				☐ Interpolation –	MSS		
	Address Matching – Other				☐ Interpolation –	SPOT		
	Census Block – 1990 – Centro				☐ Interpolation –	TM		
	Census Block Tract – 1990 – 0	Centroid			☐ Loran C			
	Census Block Tract – Other			×	☐ Public Land Su			1
	GPS Carrier Phase Static Rela				☐ Public Land Su	-	_	
	GPS Carrier Phase Kinematics				☐ Public Land Su			
	GPS Code (Pseudo Range) Di				☐ Public Land Su	•		
	GPS Code (Pseudo Range) Pro				☐ Public Land Su	•		on
	GPS Code (Pseudo Range) Sta	•	(On)		☐ Classical Surve		iniques	
	GPS, with Canadian Active C	ontrol System			☐ Zip Code – Cer			
	GPS, Unspecified		060		☐ Zip Code +2 Co			
	GPS Code (Pseudo Range) Sta	andard Position (SF	(OII)		☐ Zip Code +4 Co☐ Unknown	entrola		,
					LI Unknown			
Source	Map Scale							
	1:10,000				□ 1:62,500			
	1:12,000				□ 1:63,360			
	1:15,800				□ 1:100,000			
	1:20,000				□ 1:250,000			
	1:24,000				<b>1:500,000</b>			
	1:25,000				□ None			
	1:50,000				☐ Other			
					☑ Unknown			

## PRE-CERCLIS SCREENING ASSESSMENT CHECKLIST/DECISION FORM

This checklist can assist the site investigator during the Pre-CERCLIS screening. It will be used to determine whether further steps in the site investigation process are required under CERCLA. Use additional sheets, if necessary.

Checklist Preparer:	Dixon Wood, Geologist September 6, 2012			
	(Name/Title)	(Date)		
	MDE 1800 Washington Blvd.			
	Baltimore, MD 21230	410-537-3440		
	(Address)	(Phone)		
	dwood @mde.state.md.us			
	(E-Mail Address)			
CP4 NI	4.1.			
Site Name:	Anderson Co.			
Previous Names (if an	y):			
	-	9		
C' I I'	104 110 F W 11			
Site Location:	104-110 E. Washington Street (Street)			
	(oneer)			
	TI	MD 21740		
	Hagerstown (City)	, <u>MD</u> <u>21740</u> - (ST) (Zip)		
	(0.03)	()		
T -4144 20 640600	Longit	77 717929		
Latitude:39.640699	Longit	ude:77.717828		
Complete the following	g checklist. If "yes" is marked, please explai	n helow	YES	NO
	•	ii below.		
1. Does the site already	appear in CERCLIS?			X
2. Is the release from pr	oducts that are part of the structure of, and result in	exposure within, residential buildings or		37
businesses or commu	nity structures?			X
	of a release of a naturally occurring substance in its	unaltored form or altored galaky through		
				X
naturally occurring p	rocesses or phenomena, from a location where it is r	naturally found?		
4. Is the release into a p	ublic or private drinking water supply due to deterio	ration of the system through ordinary use?		X
5. Is some other program	n actively involved with the site (i.e., another Feder	al, State, or Tribal program)?		X
6. Are the hazardous su	ostances potentially released at the site regulated un	der a statutory exclusion (i.e., petroleum, natural		
	ls, synthetic gas usable for fuel, normal application			X
		or fermizer, forease rocated in a workplace,		1
	r regulated by the NRC, UMTRCA, or OSHA)?			
7. Are the hazardous su	ostances potentially released at the site excluded by	policy considerations (e.g., deferral to RCRA		X
Corrective Action)?				_ ^
8. Is there sufficient doc	cumentation that clearly demonstrates that there is no	o potential for a release that could cause adverse		
			5.	
	nan health impacts (e.g., comprehensive remedial in			X
above ARARs, comp	leted removal action, documentation showing that n	o hazardous substance releases have occurred		
EPA approved risk as	ssessment completed)?			
Please explain all "yes	" answer(s), attach additional sheets if neces	sary:		

Site Name: Anderson Co.

"	Y	N	N/A				
Flagged in an initiative report?	V						
WHPA in or within 1/4 mile of site (groundwater threat)?		Ø					
Proximity to residences/businesses (indoor air threat)?	V						
Site info found in ARMA files?		Ø					
Site info found in Hazardous Waste files?		Ø					
Site info found in Solid Waste files?		Ø					
Did ARMA, HW, or SW files indicate the potential for a release of hazardous substances?		Ø					
Public or domestic wells within 1/4 mile of site?		Ø					
Other potential targets (surface water bodies, sensitive populations) which might be exposed to hazardous substances from the site?	Ø						
Satellite map showing street names attached?	Ø						
NOTES:							
Flagged in Dry Cleaners Initiative Report. Level II with more than 50 years operations- Dry Cleaning							
Equipment and Suppliers. ARMA files were destroyed per document retention protocol. Oil Control files							
indicated a 500 gallon tank removal in 1999 that contained Varsol. No indication that there was any							
leakage.							

Site Determination: 

Enter the site into CERCLIS. Further assessment is recommended (explain below).

☐ The site is not recommended for placement into CERCLIS (explain below).

## **DECISION/DISCUSSION/RATIONALE:**

The Anderson Co. site is no longer an operating dry cleaner operation. Currently the three story building contains multiple apartments on the upper two floors and what appears to be a day care facility on the ground floor. A 500-gallon underground storage tank containing Varsol was removed in 1999. Based on the occupancy of the building with apartments and possible day care facility on the ground floor it is recommended that the site be placed into CERCLIS.























